



# QD/QS Release Notes Kingston 08.20.xx.00

|                |                               |
|----------------|-------------------------------|
| <b>Product</b> | Firmware Version: 08.20.27.00 |
| <b>Date</b>    | November 2017                 |

## Contents

|                                    |    |
|------------------------------------|----|
| Introduction . . . . .             | 1  |
| Purpose for This Release . . . . . | 2  |
| Resolved Issues . . . . .          | 2  |
| Known Issues . . . . .             | 12 |
| Contacting Quantum . . . . .       | 13 |

## Introduction

StorNext QD6000, QS1200, and QS2400 firmware is shipped as a bundle from Quantum. When updating to the 08.20.27.00 controller firmware, it is necessary to use SANtricity version 11.30 or later.

**Caution:** The Kingston 08.20.27.00 controller firmware is for the Pikes Peak controllers in the QD6000, QS1200, and QS2400 systems.

### COPYRIGHT STATEMENT

© 2017 Quantum Corporation. All rights reserved. Your right to copy this manual is limited by copyright law. Making copies or adaptations without prior written authorization of Quantum Corporation is prohibited by law and constitutes a punishable violation of the law. Artico, Be Certain (and the Q brackets design), DLT, DXi, DXi Accent, DXi V1000, DXi V2000, DXi V4000, DXiV-Series, FlexTier, Lattus, the Q logo, The Q Quantum logo, Q-Cloud, Quantum (and the Q brackets design), the SuperLoader, Symform, the Symform logo (and design), vmPRO, and Xcellis are either registered trademarks or trademarks of Quantum Corporation and its affiliates in the United States and/or other countries. All other trademarks are the property of their respective owners. Products mentioned herein are for identification purposes only and may be registered trademarks or trademarks of their respective companies. All other brand names or trademarks are the property of their respective owners. Quantum specifications are subject to change.



---

## Purpose for This Release

Release 08.20.27.00 is the latest firmware release and is a maintenance release. This release corrects a number of known firmware issues.

---

**Note:** Refer to SANtricity Storage Manager 11.30 Upgrade Guide (P/N: 6-68575-01 Rev A) for information about how to upgrade storage management software, controller firmware and NVSRAM, and ESM firmware in your storage array.

---

---

## Resolved Issues

This section describes the issues that were fixed in the following releases.

- [Fixes in Build 8.20.27.00](#)
- [Fixes in Build 08.20.24.00](#)
- [Fixes in Build 08.20.21.00](#)
- [Fixes in Build 08.20.20.00](#)
- [Fixes in Build 08.20.18.00](#)
- [Fixes in Build 08.20.16.00](#)
- [Fixes in Build 08.20.12.00](#)
- [Fixes in Build 08.20.11.00](#)
- [Fixes in Build 08.20.09.00](#)
- [Fixes in Build 08.20.08.00](#)
- [Fixes in Build 08.20.05.00](#)
- [Fixes in Build 08.10.15.00](#)

---

### Fixes in Build 8.20.27.00

---

Fixes in this build include:

---

#### Issue Description for 08.20.27.00

---

Controller scrolling confusing message every 30 minutes after SOD complete

---

Cache disable due to unexpected battery learn cycle during Kingston upgrade

---

Battery is reporting below 50% charge level due to invalid battery parameters and disabling cache

---

Media scan has never restarted after reconstruction.

---

Ancient IO on syncC op while synchronizing unwritten cache data to disk

---

---

**Fixes in Build  
08.20.24.00**

---

Fixes in this build include:

---

**Issue Description for 08.20.24.00**

---

Controller is accessing invalid pointer during iSCSI login.

---

Assertion failed: fullLen 0xffff, file txnMasterTransaction.cc, line 207

---

Unresponsive Pikes Peak SAS IOC -- IOC High Priority Queue full

---

Exception: Data Abort while doing pdvcRemapIOBuf

---

Drive timeout due to IOC internal deadlock

---

Assertion failed: login is NULL, file qlfclMtlInterface.cc, line 1047

---

Dual controller reboot in sasRemoveExpander

---

Make Disable VAAI Operations Work from StorageArray

---

Page fault due to dbm wasn't checking for failed memory allocation

---

Controller reboot because of Software Watch Dog Time Out.

---

PI error status not checked if the drive returns a RECOVERED ERROR sense key

---

Exception while doing "Online Port Diagnostic test " by the customer

---

Host move between 2 host group result in CmpWr op on UTM volume

---

During Read Retry of RAID 6 isolation FUA bit should be set.

---

SY-Kingston hit AIO scsiManagerOpTimerTask after 45 minutes large block, multi-threaded Straight IO

---

Check volume state in transaction lock for setTPG to avoid transfer of DEAD LUN

---

Adjustments to Taper values determine from field usage

---

Expansion tray ID changes after CFW upgrade.

---

Set thin volume's transfer permission to NO if its underlying RAID volume is dead

---

LSIP200965365 Change to decrease frequency of failing marginal batteries for Soyuz; Pikes Peak & Titan; Change to Taper Params

---

Memory fault while getting iscsi sessions

---

Exception during ASUP iscsiStateCapture collection in progress

---

MEL 7c04 A recovery point for an asynchronous mirror group was lost

---

Page Fault encountered during TDITN disconnect

---

---

**Issue Description for 08.20.24.00**

---

Recursive reboots (ASSERT) while creating ARVM relationship with very small repository

DDP is reserving more stripe than expected.

Arapaho - (ssmEvent): PANIC: SSM could not report a system event, rebooting because of memory loss.

Asserts hit during Drive FW updates at customer site

Fix memory leak in spmVerifyDatabase and spmDbShow

Overrun of Initiator PORT Objects causes controller panic loop

SOD slow due to bad communication between the two controllers

Assertion failure in  
cache::CacheManager::cacheConvertCleanToDirtyContinue

Disable Cell Balance in Legacy BBUs

Perform deep learn cycle on spare BBUs installation

Update Qinv Max T a& Min T to new threshold values in order to decrease premature BBU failure Battery

Race condition in clearACA handling results in ACA not getting cleared.

Repeating PANIC: TXN: Dual Master txn condition in  
setWriteMasterTransaction: Two instances on this controller

PANIC: clearDoorbell: IOCid:1 Fault TaskExit doorBell: x400026b6:, FWVER:  
03-00-13-00

Cache Loss due to incorrect assumptions about mismatched firmware levels

SSM: In beginSpinUp(), preincrement the child count to prevent the callback from running

---

---

**Fixes in Build  
08.20.21.00**

---

Fixes in this build include:

---

**Issue Description for 08.20.21.00**

---

Missing last digit on service tag for MD 34xx 36xx 38xx

Ancient IO on Full Thin Volume with SSD Read Cache

Running device reset results in controller restart due to ancient IO (Soyuz & Titan)

ARVM Mirror Failed due to Deltalog L0 active blocks mismatch after DVEs followed by volume ownership

Battery reports half capacity during learn cycle or recovery

---

---

**Issue Description for 08.20.21.00**

---

PANIC: Out of keyed BSEM structures.

---

Decrease frequency of OCA on Tahoe and Snowmass

---

Sudden Cacapity Drop of BBU observed on Snowmass & Tahoe

---

---

**Fixes in Build  
08.20.20.00**

---

Fixes in this build include:

---

**Issue Description for 08.20.20.00**

---

Device processing Router Solicitations failed

---

Copy-back stuck in an indefinite loop

---

rescribe multifault fails with reservation conflict write error

---

Ancient IO due to a task management request in the infiniband driver.

---

Disk pool stuck in degraded state following 2+ disk failure.

---

Drive Copy and Drive Power Cycle coincided.

---

Data inconsistency on DDP volume during Format Unit and controller power cycle

---

Operation failed, internal error.Encountered the return code 19 When Collecting DQ for ASUP

---

Brocade Switch with RDP enabled can cause IOC logout all ports and result in HIC failures and PI errors

---

Auto Contingent Allegiance (ACA) not being cleared by LUN Reset.

---

CFW should not attempt a second copy/fail if one is already running

---

Evacuation Failure and reboot leads to Data Corruption, DBM Piece Record Issue and Lockdown

---

Performance commands issued via CLI causing memory leak

---

Thin volume's default setting is 'media scan disabled'

---

Apparently incorrect length returned by PRIN READ\_KEYS

---

Cobra-D 1/18/6 Check condition results in corruption at the application layer

---

Timeouts, controller reboots and ARVM errors when SSD cache is enabled.

---

---

**Fixes in Build  
08.20.18.00**

---

Fixes in this build include:

---

**Issue Description for 08.20.18.00**

---

PI error seen from shipped IO

---

Asynchronous mirror group failed. Remote site had multiple rebooted between Controller A and B

---

Data overrun and PI guard error when cache configuration changes on an ODX Write Using Block Zero Token

---

vEOS fails to reach SOD due to Dq writer errors

---

(driverSched): ASSERT: Assertion failed: false, file qlfclExch.cc, line 1791

---

LUN initialization time estimates are significantly inaccurate

---

Integrate PL and IT Firmware Release 03.00.13.00

---

Master TXN peering failure after DVE of ARVM mirror. Probable Delta log corruption

---

Check Conditions b/44 on drive side of controller

---

ARVM Domi failure after ~2 hrs into CFDF

---

Bundle the DCM 4.9E release firmware into RAIDCore WembleyDCM.bin

---

Current Badger leaves loophole for both ESMs to malfunction at the same time

---

Loss of tray access as both ESM panicked due to invalid drawer state

---

---

**Fixes in Build  
08.20.16.00**

---

Fixes in this build include:

---

**Issue Description for 08.20.16.00**

---

Drop the charge level for a battery cell by 100 mv to fix COV

---

Controller deadlock experienced during PR WAL flush

---

PANIC ERROR: Unknown Abort type

---

Performance drops 90% for 30 seconds when TSCN runs

---

Data abort exception during iscsi HIC reset

---

Data Abort after failed DHCP on iSCSI HIC ports

---

DQ Spamming with SESDCM ESM Factory Version

---

Pagefault during vdmDrmShowMgr command

---

Data Abort in strlen

---

---

**Issue Description for 08.20.16.00**

---

CHAP username in /etc/iscsid.conf must be lower case or CFW rejects it as "CHAP\_N contains invalid chars"

RHEL 6.7 IB SY Array iSCSI IPs become unpingable after sometime

WDTO resulting in controller reboots

Battery enters a failed state even when a learn cycle is incomplete for a recoverable condition

PANIC: DSM: In 'buildNewDrive', unrecognized block size (0 bytes)

VIOS CCG defect for rebootReason/rebootReasonExtra update

Diag CCG defect for rebootReason/rebootReasonExtra update

Platforms CCG defect for rebootReason/rebootReasonExtra update

IOI2 CCG defect for rebootReason/rebootReasonExtra update

CAS CCG defect for rebootReason/rebootReasonExtra update

IOS CCG defect for rebootReason/rebootReasonExtra update

VCFG CCG defect for rebootReason/rebootReasonExtra update

---

---

**Fixes in Build  
08.20.12.00**

---

Fixes in this build include:

---

**Issue Description for 08.20.12.00**

---

PANIC: smsInsertIntoTree, on Tahoe during Volume expansion (DVE)

Page Fault in checkForAutoAbort on Pikes Peak with Infiniband HIC

Exception: Page Fault in objVerifyMagicRead

Controller firmware upgrade to 8.10.17 failed

ASSERT: Assertion failed: member < m\_NumberMembers, file utlAllocSet.cc, line 217 following firmware upgrade

MARS- KPlus drives overheating in Wembley

Drive replacement for failed ddp drive incorrectly results in 'Disk Pool Automatic Configuration' dialog

Foundations CCG defect for rebootReason/rebootReasonExtra update

Incorrect "online drive firmware download" command listed in CLI documentation (GUI Help and SMcli Guide)

Recovery Guru Procedure for "NON\_PREFERRED\_PATH" leads customer to place controller offline unnecessarily.

---

---

**Fixes in Build  
08.20.11.00**

---

Fixes in this build include:

---

**Issue Description for 08.20.11.00**

---

Repeated ancient I/O panics, 0 free bufs left.

---

Repeating Data Abort panic in  
vdm::CrushPeriodicPersistenceTaskManager::processQueue

---

iopTrack does not report host IO activity for IB hosts

---

SAS IOC dump data not available from Tahoe controller health image

---

Unable to expand disk pool volume to use the whole remaining free capacity.

---

Improve Snowmass persistent lockdown such that it allows for backup SOD if power is removed

---

Power-Fan Canister Temperature Issue

---

After a drive recovery procedure the drive is marked incompatible.

---

sysRpaChangeDedicated does not map the last page when a multi-byte request ends in the first byte of a page

---

DCE after DCR on TH results in ASSERT: Assertion failed: isExtentFree(i), file vdmCrushDrive.cc, line 416

---

RAM should clear its database when SPM clears its database.

---

Unresponsive drive after power cycle.

---

Titan controller B doesnt show up in MSW after single swap

---

CFW does not ignore comment lines when parsing staged NVSRAM for version ID

---

Shell command showSrpInfo reports incorrect "No of active RDMA channels"

---

---

**Fixes in Build  
08.20.09.00**

---

Fixes in this build include:

---

**Issue Description for 08.20.09.00**

---

PR 675142 - Ignore password reset pushbutton functionality

---

Update FPGA for all products to disable pushbutton and improve messaging

---

ODX copy can cause data corruption in Windows 2012 clustered environments with split volume and node ownership

---

**getSasErrorStatistics\_1** command continues to run after symbol command timeout

---

DA RefTag Errors logged against reads to FlashReadCache volume when handling XCOPY commands

---

---

**Issue Description for 08.20.09.00**

---

PCI SERR due to bad address during evfShowVol execution

---

Unexpected MEL 285f events during ESM 0399/039A downloads

---

SNMP Walk returns truncated data for Service Tag

---

DDC hung during collection following an AIO event

---

Unexpected MEL 285f events during ESM 0399/039A downloads

---

31+ character user label fails AMG creation with "Error 1000 - Could not communicate with the storage array"

---

Daily ASUP collection skips first event in every MAJOR-EVENT-LOG-PARTIAL

---

---

**Fixes in Build  
08.20.08.00**

---

Fixes in this build include:

---

**Issue Description for 08.20.08.00**

---

Multiple iovCopy panics due to NULL source parameter lead to cache recovery panics and lockdown.

---

Controller panic and lockdown followed by dacstor database corruption

---

EEL: Could not allocate eelHdr for ioid: 0x35918952

---

Dual Ancient IO reboot after drive replacement of a drive that is part of a large disk pool

---

Data Abort / Page Fault triggered during the capture of ionShow,99

---

State capture starves the FC driver from updating Buffer to Buffer in the fabric switch

---

Watchdog timeout during ASUP collection in fcmAnalyze

---

Many Recovered Errors: Defect List Error, Defect List not in requested format

---

WB\_CACHING\_FORCIBLY\_DISABLED Still reported in Recovery Guru after array is optimal

---

---

**Fixes in Build  
08.20.05.00**

---

Fixes in this build include:

---

**Issue Description for 08.20.05.00**

---

Handle ODFU/PDFU and Thin ICM Conflict

---

During power on of a WSAS system the fans do not operate correctly

---

Controller rebooted due to general protection fault in pentiumMsrGet following machine check exception

---

---

**Issue Description for 08.20.05.00**

---

Can't set iSNS config method as DHCP even when iSNS registration is disabled

Many Recovered Errors: Defect List Error, Defect List not in requested format

SYMagent MSW Linux services should start with systemctl when available

dssPreAllocate is not set to true when creating a new traditional RAID volume

Client timeout for disableSnapshotCollection\_1 is too short

Using the "forceTRUE" to change Synchronous Mirroring roles RPC call is not seen in the DQ

Wrong capacity calculation on disk pool automated configuration window

SYMsmInstall.Linux MSW Linux services should start with systemctl when available

OLH MSW Linux services should start with systemctl when available

Scheduled times in "show allSnapGroups schedule" are corrupted after disabling schedule

Comment Section Disappears when SMMonitor is stopped.

Installer localization process changes

---

---

**Fixes in Build  
08.10.15.00**

---

Fixes in this build include:

---

**Issue Description for 08.10.15.00**

---

CFW allowed the conversion of PI to non-PI volumes during the time when the DVE was in progress but failed.

Importing a previously exported Volume in Illinois results in Data Corruption (DPMs)

Controller lockdown due to PI errors after starting IO to a volume in a pool with flash cache and PI

"System Stall" events observed - linked to controller panic/resets with 7.

PI REFTAG off by 1 after compareAndWrite is issued to an ARVM mirror

PI Lockdown 0E+L4 Reftag off by 0x1000 in handling greater than 2MB Read

Ancient IO on sVmotion with FRC and Synchronous Mirroring active

Unreadable sectors due to PI errors after starting IO to a volume in a pool and PI

Controller panic and lockdown followed by dacstor database corruption

Change in the tray ID of an enclosure does not get updated in fdICapture output until controllers are rebooted

---

---

**Issue Description for 08.10.15.00**

---

PANIC: Driver Bug <channel:13 Adrs:x04f40100 BugCode:0x00000002>  
while creating RV

---

Watchdog Timeout from task "mtlseHealthTask" - error inside  
mtlDeviceInstance destructor Snowmass

---

PCI SERR Exception after placing a Snowmass controller offline and pulling it  
in preparation for CFW ACS test

---

Modify IO Path Statistics to provide discriminator for iSCSI logins in ITN  
statistics

---

(tShell0): PANIC: Already freed memory block at 0x19207078

---

Assertion driveList->empty() is false in evaluateHotSpare hit on  
getHotSpareCandidates\_1

---

Assertion failed: ! m\_IsMapped after drive replacement

---

Data underrun with i/o size > 2MB on only Data Assurance (PI) enabled  
volumes

---

Cannot decrease warning threshold for thin volume repository

---

srcAnalyze and tdcmdall reporting negative number for lold

---

Update SAS 3 IOC FW with fix for PowerPC 476 instruction TLB cache miss  
errata workaround

---

Page Fault and PCI\_SERR encountered on manual Thin Volume Expansion

---

Controller hits ancient I/O after command was aborted by the infiniband low  
level driver

---

Most of the IB Statistic fields are incorrectly reported as 0

---

high\_level\_volume utility write ahead log integrity fault on CFW upgrades

---

Consistency Group Snapshot fails if Snapshot Scheduler is used

---

Discovery session closure is logged as a session termination

---

Thin vol fails after repository expansion and reboot

---

6 Drives went in By-Pass mode when I reseal failed drive in Wembley with  
Soyuz

---

DDP backed volumes reporting incorrect medium characteristics in VPD page  
0xB1

---

Page Fault on bcopy when gathering DQ trace history

---

Multiple failed BBU due to OCA (overcharge alarm).

---

PANIC: mirrorWriteReadMsgAborted: Trying to double free buf 0x4fc3ff0!

---

Failed DiskPool Volumes Cannot be Recovered

---

Hardware Watchdog Timeout during straight IO on FC HIC

---

---

### Issue Description for 08.10.15.00

---

The hwLinkRate is not being presented uniformly across all PHYs.

Ancient IO on SCSI Compare and Write with T10-PI errors in USM

Unable to create disk pool due to CStripe limit

I2C memory corruption during SBB validation causing panic

Exception: Page Fault errCode: 0 pc: 0x02e680cb  
\_ZN4arvm12BitmapLOPage17isPageInialized

file mdatBitmapMetadata Assertion failed: (startBit + numBits)

ARVM Initial Sync is taking too long due to small TCP Window Size

Assertion failed: file qlfcLMtlInterface.cc, line 1085

PANIC: CrushOp persist failed!! Rebooting... during Disk Pool creation

SRP driver autoAbort handling should clean up resources owned by the chip

MEL x2047 continually being reported when media scan started during PI being disabled on Disk Pool.

Page Fault on bcopy when gathering DQ trace history

50% Performance Degradation on Tahoe FC Reads with DA enabled vs disabled.

Controller rebooted due to general protection fault in pentiumMsrGet following machine check exception

Storage array profile lists August 1970 as the controller MFG date

When a controller is upgraded from Galena to Illinois, an invalid IPv6 Link Local Address may be reported to the user.

MEL event logging of reboot reason overwritten by reset by alternate/WDTO.

Coverity Issues fix -- IO4

---

---

## Known Issues

There are no known issues specifically highlighted in the following firmware releases.

- 08.20.27.00
- 08.20.24.00
- 08.20.21.00
- 08.20.20.00

- 08.20.18.00
- 08.20.16.00
- 08.20.12.00
- 08.20.11.00
- 08.20.09.00
- 08.20.08.00
- 08.20.05.00
- 08.10.15.00

---

## Contacting Quantum

More information about this product is available on the Service and Support website at <http://www.quantum.com/ServiceandSupport/Index.aspx>. The Service and Support Website contains a collection of information, including answers to frequently asked questions (FAQs). You can also access software, firmware, and drivers through this site.

For further assistance, or if training is desired, contact the Quantum Customer Support Center:

|                      |  |
|----------------------|--|
| <b>United States</b> | 1-800-284-5101 (toll free)<br>+1-720-249-5700    |
| <b>EMEA</b>          | +800-7826-8888 (toll free)<br>+49-6131-3241-1164 |
| <b>APAC</b>          | +800-7826-8887 (toll free)<br>+603-7953-3010     |

For worldwide support:

<http://www.quantum.com/ServiceandSupport/Index.aspx>

---

