



Quantum Scalar i6000

Release Notes

Product	Scalar® i6000, Firmware Version i13.1.2
Firmware Version	767Q.GS05500
Supported Web Browsers	Firefox Chrome Microsoft Edge Apple Safari
Date	December 2018

Contents

About This Release	2
General Information	2
Security Scanners	3
Compatibility and Support	4
Resolved Issues - i13.1.2	6
Known Issues - i13.1.2	6
Documentation	9
Contacting Quantum	10

About This Release

The Scalar i6K i13.1.2 release is a maintenance release that details bug fixes described in the [Resolved Issues - i13.1.2](#) section. Refer to [Known Issues - i13.1.2](#) for additional information.

Note: The Scalar i6000 library makes a HTTPS request to a server at Quantum, once per day to check for firmware updates. Ensure port 443 is open for these outbound traffic requests.

General Information

- The Scalar library Web UI requires that the browser cache be cleared and the application re-loaded to ensure that all new functionality is implemented.
- To prevent any firmware upgrade failures when going from i12.x firmware to i13.x, make sure you are running either Java version 7 (1.7) or version 8 (1.8).
- Secure HTTPS communication protocols SSLv3, as well as TLS 1.0 and below, have been turned off due to identified security vulnerabilities such as *POODLE*. Supported browsers need to have TLSv1.1 or TLSv1.2 support enabled. TLS 1.3 is not currently supported.
- To help maintain system integrity and for marketing purposes, Quantum regularly collects system information through automatic emails. These emails contain configuration and status information only, and do not contain any customer data stored on the system. To disable this function:
 - 1 Log on to your library.
 - 2 Select **Notifications** from the **Navigation** menu.
 - 3 Select the check box next to scalartelemetrics@quantum.com in the **North Panel**.
 - 4 From the **Operation** panel, select **Reports**.
 - 5 Click the trash can icon next to **Scalar Telemetry report**.
 - 6 Click **Apply**, then **Close**.
- The Web client places a cookie on the user's computer to provide the last user's credentials upon login. The cookie only collects the user's credentials to facilitate login, and does not collect any other user data.

Special Instructions - Access Legacy Java GUI

As of firmware release i13, Scalar i6000 no longer uses the Java GUI as the default interface. However, you can use **Java Web Start** to run the legacy remote Java GUI.

Note: The legacy Java GUI will be turned off in the next release (i13.2).

Note: To run the legacy **Java Web Start** you need to be using JRE version 7 (1.7) or version 8 (1.8) and a supported browser.

- 1 In your browser, type the library IP address or library name in the address field followed by **/lmc.jnlp**.
- 2 Press **Return** to start downloading the **Library Management Console** (LMC) Java applet (some browsers will give a warning but accept the download).
- 3 Select **Show in Folder**.
- 4 Double-click the file to start the Java applet and connect to the library.

Library Default Settings

Scalar i6000 software is installed with certain default settings. This section outlines those default settings. Review this section to determine if any of the default settings need to be changed to make your library run more effectively.

WebGUI Path	Option	Default Setting
Library > Settings	Automatic Inventory	Disabled
	Library-Assisted Drive Unload	Enabled
	Logical Drive Serial Number Addressing	Enabled
	Robot Health Check Interval	Once Daily
	Tower Health Check Interval	Once Daily
	Rail Health Check Interval	Once Daily
System > Settings	Aisle Lights	Enabled (duration set to 1 hour)

Security Scanners

Quantum runs the following Security scanners against the library:

- Nessus Professional Version 7 - Version 7.0.2 (#110) WINDOWS
- insightVM 6.5.8

Compatibility and Support

Encryption Key Management Drive Support

While the Scalar i6000 library supports multiple partitions configured for encryption, only a single encryption type can be used.

Encryption Option	HP LTO-4	IBM LTO-4	HP LTO-5	IBM LTO-5	HP LTO-6	IBM LTO-6	IBM LTO-7	IBM LTO-8
Application Managed Encryption	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes
Q-EKM	No	Requires EKM License	No	Requires EKM License	No	Requires EKM License	No	No
TKLM/SKLM	No	Requires EKM License	No	Requires EKM License	No	Requires EKM License	No	Requires EKM License
SKM	Requires EKM License	No	Requires EKM License	Requires EKM License	Requires EKM License	Requires EKM License	Requires EKM License	Requires EKM License
KMIP Key Manager ¹	Requires EKM License	No	Requires EKM License	Requires EKM License	Requires EKM License	Requires EKM License	Requires EKM License	Requires EKM License
¹ - Only SafeNet, IBM SKLM and Thales encryption key servers are supported KMIP configurations								

Firmware Compatibility Matrix

The following tables show information on drive compatibility with this release of Scalar i6000. This information is current as of this product release. For the most up-to-date information on the latest qualified firmware, please visit: <http://www.quantum.com>.

IBM Drive Types	Minimum Firmware Version ¹
IBM LTO-3 (FC) 2 Gb	93GM
IBM LTO-3 (FC) 4 Gb	93GM
IBM LTO-4 (FC) 4 Gb	C7QH
IBM LTO-5 (FC) 8 Gb	H970
IBM LTO-6 (FC) 8 Gb	J450
IBM LTO-6 (FC) 8 Gb (FIPS)	J450
IBM LTO-7 (FC) 8 Gb	J4D0
IBM LTO-7 (FC) 8 Gb (FIPS)	J4D0
IBM LTO-8 (FC) 8 Gb	J4D0
IBM LTO-8 (FC) 8 Gb (FIPS)	J4D0
1. Check with Quantum Support for the latest firmware.	

HP Drive Types	Minimum Firmware Version ¹
HP LTO-3 (FC) 2 Gb	L67Z
HP LTO-3 (FC) 4 Gb	M69Z
HP LTO-4 (FC) 4 Gb	H64Z
HP LTO-5 (FC) 8 Gb	I6RZ
HP LTO-6 (FC) 8 Gb	J5KZ
1. Check with Quantum Support for the latest firmware.	

Backup Software Compatibility

To view a list of backup software packages that have been tested for interoperability with the Scalar i6000, refer to the Quantum Software Compatibility Guide at <http://www.quantum.com/swcompguide.aspx>.

Resolved Issues - i13.1.2

This release of Scalar i6000 i13.1.2 firmware resolved the following issues (bug fixes):

Change Request Number	Service Request Number	Description	Resolution
69210		Linux Kernel Hang on bad GigE configuration	Fixed.
69103		IVT fails when "unnecessary magazines" removed in Parking Modules	Fixed.
69095		Need to prevent user from importing duplicate bar code labels for cleaning media	Fixed.
69094		TDM core restarts due to too many drive dump collection threads.	Fixed.

Known Issues - i13.1.2

This release of Scalar i6000 i13.1.2 firmware has the following known issues:

Change Request Number	Service Request Number	Description	Workaround
41568	1483916	Oops in sock_common_rcvmsg in iadt driver context	If this occurred during the last reboot: 1 Close ticket and ignore. In any other case: 1 Pull a snapshot and report issue to Quantum Service. 2 Close the ticket and reboot.
42325		If a SafeNet key server(s) in a cluster is not reachable during key requests, encryption keys issued by other key servers in the cluster will not automatically replicate to the unreachable server(s) afterwards.	Users need to sync the key server cluster manually.

Change Request Number	Service Request Number	Description	Workaround
43012		When the library has an issue importing encryption keys, an error message erroneously informs users that there was a communication issue with the key server.	If communication with the key server is not impacted, the issue is that the keys cannot be imported due to being wrapped with a certificate (public key) that does not match the server's private key.
43019	297622	Local UI is missing all menu's other than Operations.	Use the Restart LMC option in the Operations tab.
43149		In some instances, during a drive firmware update and associated drive reboot, a diagnostic ticket reporting the drive has been removed may be generated.	The drive should come back online after the firmware update is complete and the diagnostic ticket will auto close. If not, follow the directions on the diagnostic ticket to troubleshoot.
51721		When canceling an IVT during an Alignment sub-test, the test result shows an Unknown SCSI error.	Ignore, no action needed.
54220		Failing control path during import with media in picker fails with TSM on AIX.	Run checkin libvolume search=yes to pickup missing media Then rerun the checkin libvolume search=bulk to import remaining media in I/E.
54220		If the control path drive fails over during an import, any media in the picker will not be discovered by TSM on AIX.	From the TSM/AIX console: 1 Run checkin libvolume search=yes to pickup missing media 2 Then rerun the checkin libvolume search=bulk to import remaining media in I/E.
54580		A single frame Series 3 control module may show the presence of two CMBs even though there is only one.	There is no negative effect to library functionality. The second CMB listed is actually the MCB.
55197		EDLM scan on import shows media is in an EDLM partition when it should be in a standard partition.	No workaround. Once the EDLM scan is complete, the media will display in it's correct partition.
60636	3603548	Email requires secure configuration/ authentication that Quantum does not support.	No workaround.
61255	3702952 3726084	In a dual robot system, in some rare cases when a robot fails, the library doesn't correctly fail over to the other robot.	Open/close the door, check for obstructions or stuck tapes.

Change Request Number	Service Request Number	Description	Workaround
63564	323683	Library is reporting a failure for a non-existent drive.	Confirm coordinates with the physical drive presence. If no physical drive is present, disregard failure and close ticket.
64753	346454	RAS ticket is issued for an incorrect firmware image on drives when file name uses lower case version number.	<ol style="list-style-type: none"> 1 Delete the drive firmware file (System > Drive Firmware). 2 Rename the drive firmware file on your workstation to have the version number in uppercase. 3 Upload that file.
64854	351347	Kernel Oops in Freescale display driver.	Oops occurred on shutdown and the library came back up without issue. Take snapshot, report issue and close ticket.
65649	355679	Drives are not set to the configured values after a system restore.	Reconfigure the incorrectly restored drives to the correct settings.
66370		Company Name field does not save when the name contains an apostrophe.	Do not use an apostrophe in the Company Name field on the Contact screen.
66624		Drive firmware auto-leveling does not happen after a drive power-cycled.	Vary-off and then Vary-on the drive. to force the auto-level.
67105		Drives automatically get varied off if taken from LME/FIPS partition to just LME partition.	This is a race condition, Wait a few minutes after removing the drives before adding them to another partition.
67287		RAS ticket report notification is in .csv file format, but uses "!" separators instead of "," separators. This causes readability issues when opening the file in Excel.	<p>Change the separator format in Windows:</p> <ol style="list-style-type: none"> 1 In Microsoft Windows, click the Start button, and then click Control Panel. 2 Open the dialog box for changing Regional and Language settings. 3 Click Additional Settings. 4 Enter ! in the List separator field. 5 Click OK twice.
67761 67762	419228	Kernel Oops issue during or after library firmware upgrade.	Additional logging has been implemented to gather more information on this issue. If the issue occurs, reboot the library and report the issue to Quantum.

Change Request Number	Service Request Number	Description	Workaround
67514		Library calibration and code roll backs.	A manual full library calibration is required for the following code roll back scenarios: <ul style="list-style-type: none"> • Pre-i13 code from i13.0.x code. • Library has i13.0.x code, a roll back to pre-i13 code occurs, and i13.0.x code is re-installed.
68824		WEBGUI has Application Managed Cleaning grayed out. This needs to be settable.	Set it to manual cleaning instead and close any RAS tickets related to cleaning.

Documentation

The following documents are currently available for the Scalar i6000.

Document Number	Document Title
Documentation Center	Scalar i6000 User's Guide
Documentation Center	Scalar i6000 Planning Guide
6-01847-xx	Quantum Encryption Key Manager User's Guide
6-01884-xx	Quantum Encryption Key Manager Release Notes
6-66532-xx	Scalar Key Manager Quick Start Guide
6-66531-xx	Scalar Key Manager User's Guide
6-66572-xx	Scalar Key Manager Safety Information by IBM
6-66535-xx	Scalar Key Manager Open Source License Agreement
6-68185-xx	RESTful Web Services API Guide
6-00423-xx	Scalar Intelligent Libraries SCSI Reference Guide
6-01159-xx	Scalar i6000 Basic SNMP Reference Guide

Contacting Quantum

More information about this product is available on the Service and Support website at www.quantum.com/support. The Service and Support Website contains a collection of information, including answers to frequently asked questions (FAQs). You can also access software, firmware, and drivers through this site.

For further assistance, or if training is desired, contact Quantum:

Quantum Technical Assistance Center in the USA:	+1 800-284-5101
For additional contact information:	www.quantum.com/support
To open a Service Request:	www.quantum.com/osr

For the most updated information on Quantum Global Services, please visit: www.quantum.com/support