Release Notes

Product: Scalar® 100 Remote Management Unit (RMU) 194A.00004
Date: July 2005

Contents

Purpose of this Release

These release notes list new features and corrections to problems that were encountered in previous releases of the Scalar 100 RMU. Visit **www.adic.com** for additional information about the Scalar 100 RMU and previous releases.

Compatibility Matrix

Refer to the following table for information on firmware compatibility with Scalar 100 Remote Management Unit (RMU) 194A.00004:

Library Firmware	Drive Firmware									
	LTO-1	LTO-2	LTO-3	AIT-2	AIT-3	DLT 7000	DLT 8000	SDLT 220	SDLT 320	SDLT 600
3.32.0002	4561	53Y2	N/A	0203_0001	0209_0001	V107	V80	v82	v82	v34
3.32.0004	N/A	N/A	N/A	0203_0001	0209_0001	N/A	N/A	v82	v82	v34
6.03.0004	4561	53Y2	54K1	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Library Firmware	AMC	SNC 5101	SNC 6101	RMU
3.32.0002	4.3	4.45.04	4.60.03	194A.00004
3.32.0004	4.3	4.45.04	4.60.03	194A.00004
6.03.0004	4.3	N/A	4.60.03	194A.00004

Resolved Issues

Problems that have been resolved in this release of the Scalar 100 RMU are as follows:

Change Request Number	Description
CR 40852	The user is logged out when accessing the `Library Command Log` from the RMU Diagnostics page.
CR 41189	The RMU does not display `Drive Firmware` versions with LTO-2 drives on 3x code.
CR 43893	Drive firmware download via the RMU does not work.
CR 43915	The RMU web page reports the library as `Online` before the library is actually online.
CR 44927	The ADIC Scalar 100 .GIF image is missing when connecting to RMU - 194A.00003.

Documentation

The following documents are currently available for the Scalar 100:

Document Number	Document Title
6-00667-05	Scalar 100 User's Guide
6-00671-02	Scalar 100 Quick Start Guide