

Release Notes

StorNext 4.6.1 M660 Metadata Appliance



6-67644-09 Rev A

Quantum StorNext M660 Release Notes, 6-67644-09 Rev A, August 2013, Product of USA.

Quantum Corporation provides this publication "as is" without warranty of any kind, either express or implied, including but not limited to the implied warranties of merchantability or fitness for a particular purpose. Quantum Corporation may revise this publication from time to time without notice.

COPYRIGHT STATEMENT

© 2013 Quantum Corporation. All rights reserved.

Your right to copy this manual is limited by copyright law. Making copies or adaptations without prior written authorization of Quantum Corporation is prohibited by law and constitutes a punishable violation of the law.

TRADEMARK STATEMENT

Quantum, the Quantum Logo, Backup. Recovery. Archive. It's What We Do., Be Certain, Be Quantum Certain, DLT, the DLT Logo, DLTSage, DLTtape, the DLTtape Logo, DXi, DXi Accent, Dynamic Powerdown, FastSense, FlexLink, GoProtect, GoVault, iLayer, Lattus, MediaShield, Optyon, Pocket-sized., Well-armored., Preserving the World's Most Important Data. Yours., Q-Cloud, Quantum Certain, Quantum Certainty, Quantum vmPRO, Scalar, SDLT, SiteCare, SmartVerify, StorageCare, StorNext, Super DLTtape, SuperLoader, and Vision are either registered trademarks or trademarks of Quantum Corporation and its affiliates in the United States and/or other countries. All other trademarks are the property of their respective owners.

Products mentioned herein are for identification purposes only and may be registered trademarks or trademarks of their respective companies. All other brand names or trademarks are the property of their respective owners.

Quantum specifications are subject to change.

Contents

Purpose of this Release		1
About This Release		2
	M660 Metadata Appliance	2
	Data Replication and Deduplication	2
	SNSM Wide Area Storage License	2
	StorNext Software Features Supported	2
	M660 Metadata Appliance File System Restrictions	2
	M660 Hardware Expansion	3
	M660 Memory Requirements	3
	Linux Device Mapper Multipath Support	3
	Configuring Clients for the M660	3
	Target Reset and Fiber Channel Tape Support on Qlogic HBAs	4
Known Issues		5
	All Metadata Appliances	5
Contacting Quantum		7

Contacting Quantum

Quantum StorNext M660 4.6.1 Release Notes 6-67644-09 Rev A August 2013



Purpose of this Release

The StorNext M660 combines industry-proven Quantum hardware and StorNext software into one convenient, out-of-the-box solution. Your M660 system has been pre-installed and is ready to operate with a minimum of additional configuration.

For upgrading to StorNext 4.6.1 on the M660 Metadata Appliance, refer to the "Update Firmware" section of Chapter 7 of the current version of the StorNext User's Guide.

This document contains additional information related to your M660 system.

For the complete list of documentation for the M660 Metadata Appliance, click the **Documentation** tab on the following web page:

http://www.quantum.com/snmdcdocs

StorNext 4.6.1 is a feature release of StorNext that is purpose-built for use with the Lattus-M Wide Area Storage product. Lattus is Quantum's next-generation object storage product, designed to meet the extreme scalability, durability, and access requirements of large-scale, long-term archives. StorNext 4.6.1 is for use ONLY by Lattus customers who want to tier data using StorNext Storage Manager into a Lattus object storage disk repository.

The complete list of documentation for StorNext 4.6.1 can be found here (click the "Select a StorNext Version" menu to view the documents for a given release of StorNext):

http://www.guantum.com/sndocs

About This Release

	This section contains important things you should know about your M660 Metadata Appliance.		
M660 Metadata Appliance	The StorNext M660 metadata controller (MDC) nodes are designed to run the MDC file system and, optionally, with the StorNext Storage Manager and the Distributed Data Mover features installed. The M660 may be configured as a Gateway server in non-Lattus environments.		
	Note: Do not enable gateway functionality for M662s connected to Lattus systems. While there are no functional issues in enabling the LAN gateway functionality within a Lattus environment, observed throughput when moving data to Lattus through the 10GbE ports will be slower than expected if this feature is enabled.		
Data Replication and Deduplication	The M660 supports the use of an optional StorNext Replication license.		
	Note: M662s used in the Lattus system need both Eth8 and Eth9 10GbE ports available for access to the Lattus "private" network. If Replication is desired, Eth5 through Eth7 1GbE ports are available.		
	The M660 is not designed for Deduplication, and the standard StorNext Deduplication license is not supported with the M660.		
SNSM Wide Area Storage License	The SNSM (StorNext Storage Manager) Wide Area Storage license is installed and can be enabled on the M662, providing access to Lattus object storage as a storage destination. This access is limited to the M662 configured for use in a Lattus system.		
StorNext Software Features Supported	With the exceptions noted above, all other optional StorNext software is supported on the M660, and is purchased separately.		
M660 Metadata Appliance File System Restrictions	The StorNext M660 does not support running NFS, or CIFS/SAMBA directly on the Metadata Appliance.		

M660 Hardware	
Expansion	

The M660 comes with unfilled expansion slots and drive bays. The M660 offers optional hardware upgrade kits for networking and disk capacity. Hardware upgrade kits require professional installation; other hardware upgrades are not supported.

M660 Memory Requirements The M660 memory allocation settings that were tested for use with MySQL in StorNext 4.3.x and later are presented in <u>Table 1</u>. Other settings may be reasonable, depending on specific conditions and workloads. However, these settings have been qualified in release testing.

Table 1 Memory Allocation Settings

	FSM BufferCacheSize	FSM InodeCacheSize	MySQL innodb_buffer_pool_size	Reserved for General Usage	Total
M660	8 GB per file system (e.g. 8 x 8 GB = 64 GB)	512 K inodes per file system (e.g. 8 x ~1 GB = 8 GB)	40 GB	32 GB	144 GB

Linux Device Mapper Multipath Support	For the StorNext M660 Metadata Appliance - StorNext 4.6.1 and later supports the standard Linux Dynamic Multipath Mapping driver (DMMP) for the metadata array and additional storage. For most configurations, the upgrade process will automatically configure the DMMP settings. If a multipath.conf file is already configured on the system, a RAS ticket will be generated and the upgrade process will be halted. Please contact Quantum Customer Support for resolution assistance. In addition:
	 Ensure that the /etc/multipath.conf file is identical on both the primary and secondary nodes of the MDC HA pair.
Configuring Clients for the M660	In order to prevent a split-brain condition between the HA pair of MDCs on the M660, at least one additional StorNext client must mount the HA file system. This will allow the additional client to "vote" in the event of a split-brain condition.
	Because the shared file system on the M660 is on the internal RAID and not visible, you must mount the client using the "diskless=yes" option.
	On Linux systems, put into the /etc/fstab an entry similar to this:
	shared-02637 /stornext/shared cvfs diskless=yes 0 0
	(The name "shared-SV1249CKD29435" used in the example will vary. The format is "shared-NNNNNNNNNNNN")
	On Windows clients, use the Mount Options field to add "diskless=yes".
	For more information about this procedure, refer to the HA chapter in the <i>StorNext User's Guide</i> .
	Note: You need to do this on only one client machine.

Target Reset and Fiber Channel Tape Support on Qlogic HBAs

The Enable SCSI Bus Target Reset parameter is enabled by default on all Fiber channel HBAs. The parameter exists for disk arrays, but poses a problem for tape drives.

PROBLEM

When the SCSI bus target (the tape drive) is reset when a backup job is running, the backup job may abort. If the tape drive does not receive the rewind and unload commands from the backup job, it leaves the tape in the drive. This may cause the drive to be seen as not ready, and then be marked offline in the backup application when the next job tries to use the drive.

SOLUTION

To disable Target Resets on the tape SAN port on the M660, the following commands can be run on each node.

- 1 Connect to each node via ssh and login using the "stornext" user ID.
- 2 Change to root user permissions by running "sudo rootsh"
- 3 Disable Target Resets on the tape SAN port by issuing "/usr/local/bin/scli -n 1 TR 0"
- 4 Confirm that the setting is correct by issuing "/usr/local/bin/scli -c" and comparing the output for Port 2. It should look like:

[root@Acadia1-1 scripts]# scli -c

Interrupt Delay Timer (100ms) : 0 Execution Throttle : 655 Login Retry Count : 8 Port Down Retry Count : 30 Enable LIP Full Login : Ena Link Down Timeout (seconds) : 30 Enable Target Reset : Ena LUNS Per Target : 128 Enable Out Of Order Frame Assembly: Dis	
Frame Size : 204 Hard Loop ID : 0 Loop Reset Delay (seconds) : 5 Enable Host HBA BIOS : Dis Enable Hard Loop ID : Dis Enable FC Tape Support : Ena Operation Mode : 0 - Interrupt Delay Timer (100ms) : 0 Execution Throttle : 655 Login Retry Count : 8 Port Down Retry Count : 30 Enable LIP Full Login : Ena Link Down Timeout (seconds) : 30 Enable Target Reset : Ena LUNS Per Target : 128 Enable Out Of Order Frame Assembly: Dis	
Hard Loop ID : 0 Loop Reset Delay (seconds) : 5 Enable Host HBA BIOS : Dis Enable Hard Loop ID : Dis Enable FC Tape Support : Ena Operation Mode : 0 - Interrupt Delay Timer (100ms) : 0 Execution Throttle : 655 Login Retry Count : 8 Port Down Retry Count : 30 Enable LIP Full Login : Ena Link Down Timeout (seconds) : 30 Enable Target Reset : Ena LUNS Per Target : 128 Enable Out Of Order Frame Assembly: Dis)
Loop Reset Delay (seconds) : 5 Enable Host HBA BIOS : Dis Enable Hard Loop ID : Dis Enable FC Tape Support : Ena Operation Mode : 0 - Interrupt Delay Timer (100ms) : 0 Execution Throttle : 655 Login Retry Count : 8 Port Down Retry Count : 30 Enable LIP Full Login : Ena Link Down Timeout (seconds) : 30 Enable Target Reset : Ena LUNS Per Target : 128 Enable Out Of Order Frame Assembly: Dis	
Enable Host HBA BIOS: DisEnable Hard Loop ID: DisEnable FC Tape Support: EnaOperation Mode: 0Interrupt Delay Timer (100ms): 0Execution Throttle: 655Login Retry Count: 8Port Down Retry Count: 30Enable LIP Full Login: EnaLink Down Timeout (seconds): 30Enable Target Reset: EnaLUNs Per Target: 128Enable Out Of Order Frame Assembly: Dis	
Enable Hard Loop ID: DisEnable FC Tape Support: EnaOperation Mode: 0 -Interrupt Delay Timer (100ms): 0Execution Throttle: 655Login Retry Count: 8Port Down Retry Count: 30Enable LIP Full Login: EnaLink Down Timeout (seconds): 30Enable Target Reset: EnaLUNS Per Target: 128Enable Out Of Order Frame Assembly: Dis	
Enable FC Tape Support: EnaOperation Mode: 0 -Interrupt Delay Timer (100ms): 0Execution Throttle: 655Login Retry Count: 8Port Down Retry Count: 30Enable LIP Full Login: EnaLink Down Timeout (seconds): 30Enable Target Reset: EnaLUNs Per Target: 128Enable Out Of Order Frame Assembly: Dis	bled
Operation Mode: 0 -Interrupt Delay Timer (100ms): 0Execution Throttle: 655Login Retry Count: 8Port Down Retry Count: 30Enable LIP Full Login: EnaLink Down Timeout (seconds): 30Enable Target Reset: EnaLUNS Per Target: 128Enable Out Of Order Frame Assembly: Dis	bled
Interrupt Delay Timer (100ms): 0Execution Throttle: 655Login Retry Count: 8Port Down Retry Count: 30Enable LIP Full Login: EnaLink Down Timeout (seconds): 30Enable Target Reset: EnaLUNs Per Target: 128Enable Out Of Order Frame Assembly: Dis	led
Execution Throttle: 655Login Retry Count: 8Port Down Retry Count: 30Enable LIP Full Login: EnaLink Down Timeout (seconds): 30Enable Target Reset: EnaLUNS Per Target: 128Enable Out Of Order Frame Assembly: Dis	Interrupt for every I/O completio
Login Retry Count : 8 Port Down Retry Count : 30 Enable LIP Full Login : Ena Link Down Timeout (seconds) : 30 Enable Target Reset : Ena LUNS Per Target : 128 Enable Out Of Order Frame Assembly: Dis	
Port Down Retry Count : 30 Enable LIP Full Login : Ena Link Down Timeout (seconds) : 30 Enable Target Reset : Ena LUNs Per Target : 128 Enable Out Of Order Frame Assembly: Dis	5
Enable LIP Full Login : Ena Link Down Timeout (seconds) : 30 Enable Target Reset : Ena LUNs Per Target : 128 Enable Out Of Order Frame Assembly: Dis	
Link Down Timeout (seconds) : 30 Enable Target Reset : Ena LUNs Per Target : 128 Enable Out Of Order Frame Assembly: Dis	
Enable Target Reset : Ena LUNs Per Target : 128 Enable Out Of Order Frame Assembly: Dis	led
LUNs Per Target : 128 Enable Out Of Order Frame Assembly: Dis	
Enable Out Of Order Frame Assembly: Dis	led
,	
	bled
HBA Instance 1: QLE2562 Port 2 WWPN 21-6	

Data Rate	:	Auto
Frame Size	:	2048
Hard Loop ID	:	0
Loop Reset Delay (seconds)	:	5
Enable Host HBA BIOS	:	Disabled
Enable Hard Loop ID	:	Disabled
Enable FC Tape Support	:	Enabled
Operation Mode	:	0 - Interrupt for every I/O completion
Interrupt Delay Timer (100ms)	:	0
Execution Throttle	:	65535
Login Retry Count	:	8
Port Down Retry Count	:	30
Enable LIP Full Login	:	Enabled
Link Down Timeout (seconds)	:	30
Enable Target Reset	:	Disabled
LUNs Per Target	:	128
Enable Out Of Order Frame Assembly	::/	Disabled

Known Issues

All	Metadata	
Ар	pliances	

<u>Table 2</u> lists the known issues for all StorNext Metadata Appliances for StorNext 4.6.1.

Table 2 Known Issues

Operating System	CR Number	SR Number	Description	Workaround (if applicable)
All	38291	n/a	In an HA failover, an Admin Alert is issued if the new primary MDC attempts to initiate an fs_fmover process on the new standby MDC while the standby MDC is still being rebooted.	Once the impacted standby MDC finishes rebooting and becomes functional again, use fsddmconfig (or the GUI) from the master MDC to re-enable DDM for the standby MDC, as follows: # fsddmconfig -u -s e standby_mdc_hostname
Linux	37538	1398524	GUI is unable to down a stripe group when LUNs are unavailable	Mark stripe groups down in the GUI before taking the stripe group's disks offline. If that is not possible, set the stripe group down directly through the FSM configuration file and restart the FSM. See the snfs_config(5) man page or the MAN Pages Reference Guide for details.

Quantum StorNext M660 4.6.1 Release Notes 6-67644-09 Rev A August 2013

Operating System	CR Number	SR Number	Description	Workaround (if applicable)
Linux	38128	1395540	Using the GUI while a large Media import is kicked off via the command line can cause the GUI to timeout or crash.	Wait until a bulk load from tape is finished prior to opening the StorNext GUI.
Linux	29098/ 37916	n/a	Admin alerts are generated for network or FC ports that are disconnected but are configured in the system.	The only way to prevent these alerts from displaying is to remove the network or FC ports that are disconnected from your configuration, unless the ports will only be down temporarily.

Contacting Quantum

More information about this product is available on the Quantum Service and Support website at <u>www.quantum.com/ServiceandSupport</u>. The Quantum Service and Support website contains a collection of information, including answers to frequently asked questions (FAQs). You can also access software, firmware, and drivers through this site.

For further assistance, or if training is desired, contact Quantum Technical Assistance Center.

North America	1 800-284-5101 (toll free) 1-720-249-5700
EMEA	+00800 7826 8888 (toll free) +49 6131 3241 1164
APAC	1-800-7826-8887 (toll free) +603-7953-3010
Service and Support Web Site	www.quantum.com/ ServiceandSupport
Online Service Request System	www.quantum.com/OSR

(Local numbers for specific countries are listed on the Quantum Service and Support Website.)

Quantum StorNext M660 4.6.1 Release Notes 6-67644-09 Rev A August 2013